THIS CIRCUIT DOESNT WORK.....RECEIVED PULSES AT RA3 ARE INCORRECT.




THIS CIRCUIT WORKS FINE AND GIVES CORRECT RA3 RECEIVED PULSES




POTENTIAL IMPROVEMENTS.....FROM LOWEST COMPONENT COUNT TO HIGHER COMPONENT COUINT

A




I HOPE THIS CIRCUIT WORKS, AS IT MEANS WE DONT HAVE TO RE-SPIN THE BOARD.

B




C




D




--- C:\forum\dali prob\DALI circuit improvements.asc ---