

(2), 4.7uF/50V caps. Replaced due to high ESR value.

